Brookhaven

High Water Mark Field Form

(one form per HWM)

SUF-636
Quick Lookup #

DATE: 11/6/2012 STORM: SANDY PARTY: IF & GEK

SITE INFORMATION

SITE NAME: HWM-NY-SUF-636 **LATITUDE (DD to 6 places):** 40.76451
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 33 Astor Avenue side of house great seed line **LONGITUDE (DD to 6 places):** 072.91386

STATE: NY **COUNTY:** SUFFOLK **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake), disc, spray paint, other_____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 2.59 from l.s.
Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: HWM visible on side of house b/w siding and porch.
2.59' from ground surface & 2.51' from top of stake to HWM

HWM Elevation: 5.40 ft

RM Description: ~~stake flush w/ ground~~ stake in ground. 0.8 ft from land surface

RM #: ____ **RM Elevation:** _____

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** IF

Digital Photo Filenames: HWM-NY-SUF-636-(01-06).jpg

Please complete site sketch on reverse

Pt 51 5.155 vp= 0.073
Pt 52 5.180 vp= 0.063

Average = 5.168

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/06/2012 STORM: Sandy PARTY: JF & GEK

SITE MAP



Additional Notes: