Westhampton Beach

High Water Mark Field Form

(one form per HWM)

SUF-637
Quick Lookup #

DATE: 11/6/2012 STORM: Sandy PARTY: IF & GEK

SITE INFORMATION

SITE NAME: HWM-NY-SUF-637 **LATITUDE (DD to 6 places):** 40.79022
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: INSIDE PARKING LOT OF DUNE DECK BY FENCE **LONGITUDE (DD to 6 places):** 072.66212

STATE: NY **COUNTY:** SUFFOLK **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, (permanent marker), stake, disc, spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.42 ft from bottom of cement block to HWM
Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Excellent seed line present on fence inside parking lot of DUNE DECK

HWM Elevation: 6.42 ft

RM Description: 1.42 ft from top of cement block to HWM on fence
cement block is 1.2 ft from base to top of cement block.

RM #: _____ **RM Elevation:** _____

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** IF

Digital Photo Filenames: HWM-NY-SUF-637-(01-11).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/6/2012 STORM: SANDY PARTY: IF & GEK

SITE MAP



Additional Notes: