Nissequogue

High Water Mark Field Form

(one form per HWM)

SUF-944
Quick Lookup #

DATE: 11-04-12 STORM: SANDY PARTY: SCF + JSF

SITE INFORMATION

SITE NAME: HWM-NY-SUF-944 **LATITUDE (DD to 6 places):** 40.83260
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 416 River Rd Nissequogue, NY **LONGITUDE (DD to 6 places):** -073.19342

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other no mark
Type of mark: debris line, mud line, (seed line), wash line, other
Mark location (circle one): (Inside) Outside **Approx. height above ground (ft):** 2.82 above deck
Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line located on glass pane in side door. *If possible back into/down driveway. It will help you when leaving.

HWM Elevation: 8.917

RM Description: top of wooden pier on 2nd bulkhead to the west next to house #416 on Nissequogue River Rd

RM #: TBM1 **RM Elevation:** 7.357

Other Notes:
HWM Seed line elev. in window transposed to western railing + marked w/ ✗

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:**

Digital Photo Filenames: HWM-NY-SUF-944-(01-06).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11-04-12 STORM: SANDY PARTY: Shawn + Jason

SITE MAP



Additional Notes:

HWM on glass window on side door. Follow deck around.

No physical mark → refer to pictures.

Find side door, and measured from deck.