Bay Shore
(one form per HWM)

High Water Mark Field Form

SUF-949
Quick Lookup #

DATE: 11-05-12 STORM: SANDY PARTY: Shawn & Jason (SCF + JSF)

SITE INFORMATION

SITE NAME: HWM-NY-SUF-949 **LATITUDE (DD to 6 places):** 40.62819
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Robert Moses State Park Near electrical Area on Northside - Across street from Parking Field #4 **LONGITUDE (DD to 6 places):** -073 24333

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake), disc, (spray paint), other
Type of mark: (debris line), mud line, seed line, wash line, other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):**
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) (Poor (>0.25 ft))

ELEVATION INFORMATION

HWM Description: HWM is debris line on pathway to LIPA Electric Area Stake visible above ground level along with orange spray paint. Directions detailed on back.

HWM Elevation: 5.61

RM Description: Anchor bolt set in Asphalt pavement approx 6 ft Seaward of HWM and 11' South of gate to Electrical Area.

RM #: 1 **RM Elevation:** 5.398

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:**

Digital Photo Filenames: HWM-NY-SUF-949-(01-05).jpg
HWM-NY-SUF-949-(06-08)alt.jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11-05-12 STORM: SANDY PARTY: Shawn + Josh

SITE MAP



Additional Notes:

Pathway accessible from Robert Moses Causeway, heading West. Must make left at lighthouse, head east, and wrap around. Orange spray paint is located outside LJPA Entrance fence. Alternate stake @ ground level.