Oak Beach

High Water Mark Field Form

(one form per HWM)

go back

SUF-950
Quick Lookup #

DATE: 11-05-12 STORM: SANDY PARTY: Shawn + Jason (SCF+JSF)

SITE INFORMATION

SITE NAME: HWM-NY-SUF-950 **LATITUDE (DD to 6 places):** 40.63977
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 4263 Lot#5 Oak Beach Rd **LONGITUDE (DD to 6 places):** -073.28816

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other
Type of mark: debris line, mud line, seed line, wash line, other
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 5.52 from top of stake @ ground level
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line under back deck, on post. Stake located next to back basement door, @ ground level.

HWM Elevation: 7.752

RM Description: scribed X on top of cap of fire Hydrant located 120 ft south of driveway to 4263 Oak beach Rd on land side of Road.

RM #: 1 **RM Elevation:** 5.168

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:**

Digital Photo Filenames: HWM-NY-SUF-950-(01-04).jpg
HWM-NY-SUF-950-(05-08)alt.jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11-05-12 STORM: SANDY PARTY: Shawn & Jason

SITE MAP



Additional Notes:

* Water came from the South. Both stakes at ground level.
Alternate water mark on side of house.