Amityville

(one form per HWM)

High Water Mark Field Form

SUF-956
Quick Lookup #

DATE: 11-05-12 STORM: SANDY PARTY: Shawn & Jason (SCF + JSF)

SITE INFORMATION

SITE NAME: HWM-NY-SUF-956 **LATITUDE (DD to 6 places):** 40.66481
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 200 S. Ketcham Ave Amityville NY **LONGITUDE (DD to 6 places):** -073.42332

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake), disc, spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** .96 from top of stake
Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line located on North side of house. Stake at ground level.

HWM Elevation: 7.482 ft above NAVD88

RM Description: Square cut on east side of S. Ketcham and Marion Rd. In front of Fire hydrant.

RM #: 23 **RM Elevation:** 5.062 ft above NAVD88

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** _____

Digital Photo Filenames: HWM-NY-SUF-956-(01-03).jpg
HWM-NY-SUF-956-(04-06)alt.jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/05/12 STORM: SANDY PARTY: Shawn & Jason

SITE MAP



Additional Notes:

Address 200 Ketcham Ave Amityville
Both stakes at ground level. Alternate located
South of door.