Southold

High Water Mark Field Form

(one form per HWM)

SUF-959
Quick Lookup #

DATE: 11/06/12 STORM: Sandy PARTY: STL/SCF

SITE INFORMATION

SITE NAME: HWM-NY-SUF-959 **LATITUDE (DD to 6 places):** 41.03709
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 2850 Cedar Beach Rd **LONGITUDE (DD to 6 places):** -72.39347

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 0.83 ft
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line on foundation of garage at 2850 Cedar Beach Rd.

HWM Elevation: 6.55 ft.

5.722 (survey marker)
0.83
6.552

RM Description: _____

RM #: _____ **RM Elevation:** 6.81 ft.

Other Notes: _____

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** _____

Digital Photo Filenames: HWM-NY-SUF-959-(01-03).jpg
HWM-NY-SUF-959-(04-06)alt.jpg

Please complete site sketch on reverse

6.641

(1) 6.812 V 0.038
(2) 6.799 V: = 0.045
13.611
6.806

High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

_____

_____

_____

_____