Southold

High Water Mark Field Form

(one form per HWM)

SUF-960
Quick Lookup #

DATE: 11/06/12 STORM: Sandy PARTY: STL/SCF

SITE INFORMATION

SITE NAME: HWM-NY-Suf-960 **LATITUDE (DD to 6 places):** 41.03756
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 3050 Minnehaha Blvd. **LONGITUDE (DD to 6 places):** -72.42766

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake), disc, spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.07
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line on exterior entrance gate of 3050 Minnehaha Blvd.

HWM Elevation: 6.91 ft.

5.840 (stake
+1.07
6.91

RM Description: _____

RM #: _____ **RM Elevation:** _____

(1) 4.938 v: = 0.069
(2) 5.115 v: = 0.057
(3) 5.160 v: = 0.039

Other Notes: _____

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** SCF

Digital Photo Filenames: HWM-NY-SUF-960-(01-03).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

_____

_____

_____

_____