Babylon

High Water Mark Field Form

(one form per HWM)

SUF-965
Quick Lookup #

DATE: 1/3/12 3 STORM: Sandy PARTY: ADL + SCF

SITE INFORMATION

SITE NAME: HWM - NY-SUF-965 **LATITUDE (DD to 6 places):** 40.634165
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Town DPW maintence garage **LONGITUDE (DD to 6 places):** -073.345257

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other_____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): (Inside) Outside **Approx. height above ground (ft):** 0.78'
Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Excellent seed line on door inside Town of Babylon maintance garage; parking lot and entrance shared w/ HWM-NY-SUF-951

HWM Elevation: 5.217

RM Description: Mag nail and survey marker circled in orange paint near chain link fence post of fenced area east of garage doors

TBM
RM #: 1 **RM Elevation:** 4.105

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** ADL, AES

Digital Photo Filenames: HWM - NY - SUF - (01 - 08).jpg
AES, GPS levels: - 09 to - 014

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

SWF-965
Quick Lookup #

DATE: 1/3/13 STORM: Sandy PARTY: ADL + SCF

SITE MAP



Additional Notes: