(RYE)

High Water Mark Field Form

(one form per HWM)

WES-815
Quick Lookup #

DATE: 11/06/12 STORM: Sandy PARTY: RRB, MLN

SITE INFORMATION

SITE NAME: HWM-NY-WES-815 **LATITUDE (DD to 6 places):**
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Tide Hill Yatch Basin RYE NY **LONGITUDE (DD to 6 places):**

STATE: NY **COUNTY:** Westchester **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other pencil
Type of mark: debris line, mud line, seed line, wash line, other
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 3.01 ft
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: HWM is a seed line in the office on west wall of Tide Hill Yacht Basin on Kirby lane, Rye NY

HWM Elevation: 9.816 ft above NAVD88

RM Description: USGS Mag nail in ~ 5 ft east of sea wall ~ 25 ft South of Tide Mill Yacht Basin

RM #: 8 **RM Elevation:** 6.096 ft Above NAVD88

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** MLN

Digital Photo Filenames: HWM-NY-WES-815(01-04).Jpeg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

(UTM Coord.) - N 1488594 1.541 f E 200 8737.432 ft