High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/5/12 STORM: SANDY PARTY: CJH/ACD

SITE INFORMATION

SITE NAME: HWM-NY-WES-980 **LATITUDE (DD to 6 places):** 40.94742
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: _____ **LONGITUDE (DD to 6 places):** 73.73238

STATE: NY **COUNTY:** Westchester **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other concrete anchor
Type of mark: debris line, mud line, seed line, wash line, other _____
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 0.34
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Good seed line on inside of concrete water pipe surround that is to the west of the large boat ramp.

HWM Elevation: 10.258

RM Description: _____

RM #: _____ **RM Elevation:** _____

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** CJH

Digital Photo Filenames: HWM-NY-WES-980 (1)
HWM-NY-WES-980 (2)

Please complete site sketch on reverse

10.245
+10.271
2/ 10.258

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/5/12 STORM: SANDY PARTY: CJH/ACD

SITE MAP



Additional Notes:

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS
HWM980	3.392	13.650		10.258	
Wes-100			7.928	5.722	
TP1	7.622	13.679	7.593	6.057	
Wes-100			7.956	5.723	
HWM980			3.421	10.258	

11/5/12

ACD/CJH

HWM-NY-Wes-980

Hobo is 555-NY-Wes-100

RDG

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS

Remarks