High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11/1/2012 STORM: SANDY PARTY: CCR/JMD

SITE INFORMATION

SITE NAME: HWM-VA-ACC-052 **LATITUDE (DD to 6 places):** _____
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: _____ **LONGITUDE (DD to 6 places):** _____

STATE: _____ **COUNTY:** _____ **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other N/A
Type of mark: debris line, mud line, seed line, wash line, other _____
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** _____
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line and mud stain on outside of garage.

HWM Elevation: 5.93 ft, NAVD 88

RM Description: _____

RM #: 1 **RM Elevation:** 3.98 ft, NAVD 88

Other Notes:
TD = 1.73

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** CCR

Digital Photo Filenames: ~~101-043~~ HWM-VA-ACC-052-pic 1

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/01/2012 STORM: SANDY PARTY: CCR/JMD



Additional Notes:

Use sketch w/ 51-53. OPUS 1353-1430 on HUB-1.

RM-1 Elev = 3.363 ft, NAVD 88

M.K. Miles 703-328-2898 offset: 3.977 ft

James Fox 434-579-3096