# High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/2012 STORM: SANDY PARTY: CCR/JMD

## SITE INFORMATION

**SITE NAME:** HWM-VA-ACC-055 **LATITUDE (DD to 6 places):** 37.72195
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

**SITE DESCRIPTION:** HOLLY CREEK **LONGITUDE (DD to 6 places):** 75.78580°

**STATE:** VA **COUNTY:** ACCOMACK **Landowner notified (circle one):** (Yes) No

## HWM INFORMATION

**HWM identified with:** colored flagging, marker, stake, disc, spray paint, other N/A
**Type of mark:** debris line, mud line, (seed line), wash line, other
**Mark location (circle one):** (Inside) Outside **Approx. height above ground (ft):** 0.8
**Quality of mark (circle one):** Excellent (+/- 0.05 ft) (Good) (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

## ELEVATION INFORMATION

**HWM Description:** Seed line on inside door of storage shed.

**HWM Elevation:** 5.12 ft, NAVD 88

**RM Description:**

~~RM #:~~ HUB-1 HUB ~~RM~~ **Elevation:** 5.66 ft, NAVD 88

**Other Notes:**
Not wave effected

## PHOTOGRAPH INFORMATION

**Pictures Taken:** (Yes) No **Camera Owner:** CCR

**Digital Photo Filenames:** ~~101-054~~ HWM-VA-ACC-055_pic1

Please complete site sketch on reverse

# High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/2012 STORM: SANDY PARTY: CCR/JMD




**Additional Notes:**

RM-1 is chisel square on brick foundation of storage shed, in doorway, on left side looking in.
OPUS: 0958~1046