High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/2012 STORM: SANDY PARTY: CCR/UMD

SITE INFORMATION

SITE NAME: HWM-VA-ACC-056 **LATITUDE (DD to 6 places):** 37.72195°
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: HOLLY COVE **LONGITUDE (DD to 6 places):** 75.78580°

STATE: VA **COUNTY:** ACCOMACK **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other N/A
Type of mark: debris line, mud line, seed line, (wash line), other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** ∅
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) (Fair) (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Wash line on berm next to creek on eastern side of property.

HWM Elevation: 5.08 ft, NAVD 88

RM Description:

~~**RM#:**~~ HUB-1 ~~**RM**~~ HUB **Elevation:** 5.66 ft, NAVD 88

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** CCR

Digital Photo Filenames: ~~lot-055~~ HWM-VA-ACC-056_pic1
~~lot-056~~ HWM-VA-ACC-056_pic2

Please complete site sketch on reverse

See HWM-055 for sketch

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/2012 STORM: SANDY PARTY: CCR/JMD



Additional Notes:

RM-1 is chisel square on brick foundation of storage shed, in doorway, on left side looking in.
OPUS: 0958~1046