High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/2012 STORM: SANDY PARTY: CCR/JMD

SITE INFORMATION

SITE NAME: HWM-VA-ACC-057 **LATITUDE (DD to 6 places):** 37.66615°
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: HARBORTON **LONGITUDE (DD to 6 places):** 75.83120°

STATE: VA **COUNTY:** ACCOMACK **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other_____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.22
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good) (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line on outside of fenced-in enclosure near public boat ramp.

HWM Elevation: 5.02 ft, NAVD 88

RM Description: PK Nail on asphault, 5 ft E of boat ramp, next to telephone pole. GPS point 1307-

RM #: 1 **RM Elevation:** 3.83 ft, NAVD 88

Other Notes:
Wave effected

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** CCR

Digital Photo Filenames: ~~101-0060~~ HWM-VA-ACC-057_pic1

Please complete site sketch on reverse

GPS file : 90323074
RM-1 Elev = 3.83 ft, NAVD 88
(offset = 6.548 ft)

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/12 STORM: SANDY PARTY: CCR / DMD

SITE MAP



Additional Notes:

057-058