High Water Mark Field Form

(one form per HWM)

NFK ~~NAR~~-004
Quick Lookup #

DATE: 11/2/2012 STORM: SANDY PARTY: RBB/ALH

SITE INFORMATION

SITE NAME: HWM - VA - ~~NOR~~ NFK - 004 **LATITUDE (DD to 6 places):** 36°57'33.3
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Sarah Constant park wash line - Norfolk, VA **LONGITUDE (DD to 6 places):** 076°15'32.5

STATE: VA **~~COUNTY~~:** City of Norfolk **Landowner notified (circle one):** Yes (No) - city owned

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other Not marked
Type of mark: (debris line) mud line, seed line, wash line, other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 0
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Debris line on beach behind dunes

HWM Elevation: 7.56 ft, NAVD 88

RM Description: Chisled square on corner of curb in parking lot to the west of Sarah Constant Stone Marker

RM #: 1 **RM Elevation:** 10.56ft (NAVD 88)

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** USGS VAWSC

Digital Photo Filenames: 102-389 — 102-397

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

NOR-004
Quick Lookup #

DATE: 11/2/2012 STORM: SANDY PARTY: RBB / ALH

SITE MAP



Additional Notes: