High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/12 STORM: SANDY PARTY: CCR/JMD

SITE INFORMATION

SITE NAME: HWM-VA-NOR-051 **LATITUDE (DD to 6 places):** 37.55695°
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: SHIELDS BRIDGE **LONGITUDE (DD to 6 places):** 75.83983°

STATE: VA **COUNTY:** North Hampton **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other N/A
Type of mark: debris line, mud line, seed line, (wash line), other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 0
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) (Fair) (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Washline on roadside, western side of bridge.

HWM Elevation: 3.10 ft, NAVD 88

RM Description: HUB- Temporary GPS Point - 1545-1615
RM-1 - PK Nail on North side of road, east side of bridge at end of guard rail.

RM #: 1 **RM Elevation:** 5.62 ft, NAVD 88

Other Notes:
Wave effected

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** CCR

Digital Photo Filenames: ~~101-0062~~ HWM-VA-NOR-051-pic1
~~101-0063~~ HWM-VA-NOR-051-pic2

Please complete site sketch on reverse

GPS file: 90323076
HUB elev: 2.474 ft, NAVD 88
(offset = 4.38 ft)

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/12 STORM: SANDY PARTY: CCR/JMD

SITE MAP



Additional Notes:

NOR-051