

Isaac Recovery 9-3-12

DAL/ASG/PHN

HWM-LA-STJ-206

golf course

lat $30^{\circ} 5' 4.9''$

long $70^{\circ} 29' 13.2''$

HWM1 6.960

HWM2 6.962

AVG 6.961

Good HWM

Tipping Bucket Precipitation Sensor Test Calibration Form

Station Number: _____ Party: _____

Station Name: _____

Manufacturer/Model No: _____

Serial Number: _____

Calibration Date: _____ Calibration Time: _____

Test Number	Nozzle Size	Volume (mL)	Expected Tips	Observed Tips
1				
2				

Is a correction needed based on calibration? Yes _____ No _____

Was gage level on arrival? Yes _____ No _____

Was funnel free of obstructions on arrival? Yes _____ No _____

Does funnel have an unobstructed view of sky? Yes _____ No _____

The funnel and tipping buckets should be cleaned. The counterweight and bucket stops should be checked. If the gage was leveled, it should be noted in the Remarks. If No is answered above, an explanation should be in the Remarks.

Remarks (include any adjustments made to the instrument, if any):
